

Dusty Conditions on FSR

Location: Bamfield (west Vancouver Island)

Date of Incident: June 5, 2020

Details of Incident: A driver, experienced with operating on resource roads, drove into the back of a logging truck that was travelling in the same direction. Reports indicate that the dusty conditions limited visibility. Luckily the driver was not seriously injured.

Recommended Preventative Actions:

- Drive to conditions (including limited visibility)
- Give yourself adequate time to reach your destination
- Travel with headlights and taillights turned on
- Report unsafe conditions to the appropriate road permit holder

For more information: Resource Road Driving



<u>Click here</u> to access this safety alert from our website.

BCFSC welcomes all incident or near-miss submissions. If you have an incident you'd like to share or would like to subscribe to the **Industry Safety Alert** <u>click here</u>. BCFSC will review and remove all identifying information to protect your privacy.

Connect With Us: bcforestsafe.org | Facebook | Twitter | YouTube | LinkedIn | Instagram

Disclaimer: Industry Alerts are voluntarily submitted by workers or companies. We encourage the sharing of information that can help improve safety for all workers. The BC Forest Safety Council is not responsible for accuracy of content.



Main Office: 420 Albert Street, Nanaimo, BC, V9R 2V7 Central BC: 2666 Queensway, Prince George, BC, V2L 1N2 Toll Free: 1.877.741.1060 | bcforestsafe.org