



# INDUSTRY SAFETY ALERT

## Train and Logging Truck Collision

**Location:** Naver Creek Road (North of Quesnel)

**Date of Incident:** June 10, 2020

**Details of Incident:** An Eastbound loaded logging truck was crossing a marked rail crossing when a southbound freight train collided with the trailer. The truck and trailer flipped onto its side spilling the logs into the ditch.

### **Recommended Preventative Actions:**

- Avoid complacency
- Expect the unexpected
- Never attempt to beat the train at a crossing
- When approaching a railroad crossing, slow down, look both ways, and listen for a train on the tracks
- Never stop on railroad tracks. Keep moving once you have entered the crossing
- Reduce the risk of stalling by not shifting gears on the tracks.



---

[Click here](#) to access this safety alert from our website.

BCFSC welcomes all incident or near-miss submissions. If you have an incident you'd like to share or would like to subscribe to the **Industry Safety Alert** [click here](#). BCFSC will review and remove all identifying information to protect your privacy.

Connect With Us: [bcforestsafesafe.org](https://bcforestsafesafe.org) | [Facebook](#) | [Twitter](#) | [YouTube](#) | [LinkedIn](#) | [Instagram](#)

Disclaimer: Industry Alerts are voluntarily submitted by workers or companies. We encourage the sharing of information that can help improve safety for all workers. The BC Forest Safety Council is not responsible for accuracy of content.



**BC Forest Safety**

Main Office: 420 Albert Street, Nanaimo, BC, V9R 2V7  
Central BC: 2666 Queensway, Prince George, BC, V2L 1N2  
Toll Free: 1.877.741.1060 | [bcforestsafesafe.org](https://bcforestsafesafe.org)